

Final Reclamation Inspection

November 11, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 336527

Inspection Document #: 697503514

Weld County, CO

NESE Section 25 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CENTEX #10-25
Location ID: 336527



Photo 1. Photo taken from the well location, facing West. Photo illustrates that only 3 wells remain at location.

Inspection Photos
Location Name: CENTEX #10-25
Location ID: 336527



Photo 2. Photo taken from the associated tank battery, facing East. Photo illustrates the tank battery is still in use for other active wells.



Photo 3. Photo taken from the associated tank battery, facing North. See comments under Photo 2.