

Inspection Photos
Location Name: Leidy Barnes A #1
API: 05-067-06969



Leidy Barnes A #1 location photo.



Leidy Barnes A #1 well head.

Inspection Photos
Location Name: Leidy Barnes A #1
API: 05-067-06969



PBV does not have labels as required by Rule 605.h.



Excavation to expose flow lines being decommissioned as part of REM #20366.