

# Reclamation Inspection

November 11, 2021

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 480698

Inspection Document #: 697503518

Weld County, CO

NWSE Section 11 T1N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

# Inspection Photos

Location Name: Martin J Schaefer #2 Flowline

Location ID: 480698



**Photo 1.** COGCC drone aerial imagery taken on November 11, 2021 documenting the current status of the remediation work and documenting the potential reclamation scope. This image is of the western to approximate central remediation extent.



## Inspection Photos


Location Name: Martin J Schaefer #2 Flowline

Location ID: 480698



**Photo 2.** COGCC drone aerial imagery taken on November 11, 2021 documenting the current status of the remediation work and documenting the potential reclamation scope. This image is of the eastern to approximate central remediation extent.

Inspection Photos  
Location Name: Martin J Schaefer #2 Flowline  
Location ID: 480698



**Photo 3.** Google Earth aerial imagery from 6/10/2021 illustrates conditions prior to the flowline spill.



Inspection Photos  
Location Name: Martin J Schaefer #2 Flowline  
Location ID: 480698



**Photo 4.** Google Earth aerial imagery from 6/10/2021 illustrates conditions prior to the flowline spill.