

Inspection Photos
Location Name: La Posta Canyon #4
API: 05-067-06291



La Posta Canyon #4 PA marker.



Close up of cut off well head and PA marker.

Inspection Photos
Location Name: La Posta Canyon #4
API: 05-067-06291



PBV contained fluids and was unable to be moved at the time of this inspection.



Flow lines marked for excavation and removal.