

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/22/2021

Submitted Date:

11/22/2021

Document Number:

699304520

**FIELD INSPECTION FORM**

Loc ID 330697	Inspector Name: Revas, Robbie	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 20 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																																															
<b>Operator Information:</b> OGCC Operator Number: 10633 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC Address: 1801 CALIFORNIA STREET #2500 City: DENVER State: CO Zip: 80202																																																																																																																			
<b>Contact Information:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>,</td> <td></td> <td>Cogcc.inspections@crestone pr.com</td> <td><a href="#">All Inspections</a></td> </tr> </table>				Contact Name	Phone	Email	Comment	,		Cogcc.inspections@crestone pr.com	<a href="#">All Inspections</a>	<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>																																																																																																							
Contact Name	Phone	Email	Comment																																																																																																																
,		Cogcc.inspections@crestone pr.com	<a href="#">All Inspections</a>																																																																																																																
<b>Inspected Facilities:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>251674</td><td>WELL</td><td>SI</td><td>02/01/2021</td><td>GW</td><td>123-19477</td><td>RODMAN-BRUNTZ 12-26</td><td>SI</td></tr> <tr><td>419180</td><td>WELL</td><td>SI</td><td>02/01/2021</td><td>GW</td><td>123-32168</td><td>RODMAN BRUNTZ 22-26</td><td>SI</td></tr> <tr><td>419189</td><td>WELL</td><td>SI</td><td>02/01/2021</td><td>GW</td><td>123-32172</td><td>RODMAN BRUNTZ 11-26</td><td>SI</td></tr> <tr><td>419193</td><td>WELL</td><td>SI</td><td>02/01/2021</td><td>GW</td><td>123-32175</td><td>RODMAN BRUNTZ 0-2-26</td><td>SI</td></tr> <tr><td>419208</td><td>WELL</td><td>SI</td><td>02/01/2021</td><td>GW</td><td>123-32182</td><td>RODMAN BRUNTZ 0-4-26</td><td>SI</td></tr> <tr><td>419218</td><td>WELL</td><td>SI</td><td>07/01/2021</td><td>GW</td><td>123-32188</td><td>RODMAN BRUNTZ 2-0-26</td><td>SI</td></tr> <tr><td>419240</td><td>WELL</td><td>SI</td><td>02/01/2021</td><td>GW</td><td>123-32197</td><td>RODMAN BRUNTZ 2-4-26</td><td>SI</td></tr> <tr><td>473689</td><td>OFF- LOCATION FLOWLINE</td><td>AC</td><td>03/31/2021</td><td></td><td>-</td><td>Wellhead Line 26H-D266 FAC</td><td>AC</td></tr> <tr><td>473690</td><td>OFF- LOCATION FLOWLINE</td><td>AC</td><td>03/31/2021</td><td></td><td>-</td><td>Wellhead Line 26H-D266 FAC</td><td>AC</td></tr> <tr><td>473691</td><td>OFF- LOCATION FLOWLINE</td><td>AC</td><td>03/31/2021</td><td></td><td>-</td><td>Wellhead Line 26H-D266 FAC</td><td>AC</td></tr> <tr><td>473692</td><td>OFF- LOCATION FLOWLINE</td><td>AC</td><td>03/31/2021</td><td></td><td>-</td><td>Wellhead Line 26H-D266 FAC</td><td>AC</td></tr> <tr><td>473693</td><td>OFF- LOCATION FLOWLINE</td><td>AC</td><td>03/31/2021</td><td></td><td>-</td><td>Wellhead Line 26H-D266 FAC</td><td>AC</td></tr> <tr><td>473694</td><td>OFF- LOCATION FLOWLINE</td><td>AC</td><td>03/31/2021</td><td></td><td>-</td><td>Wellhead Line 26H-D266 FAC</td><td>AC</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	251674	WELL	SI	02/01/2021	GW	123-19477	RODMAN-BRUNTZ 12-26	SI	419180	WELL	SI	02/01/2021	GW	123-32168	RODMAN BRUNTZ 22-26	SI	419189	WELL	SI	02/01/2021	GW	123-32172	RODMAN BRUNTZ 11-26	SI	419193	WELL	SI	02/01/2021	GW	123-32175	RODMAN BRUNTZ 0-2-26	SI	419208	WELL	SI	02/01/2021	GW	123-32182	RODMAN BRUNTZ 0-4-26	SI	419218	WELL	SI	07/01/2021	GW	123-32188	RODMAN BRUNTZ 2-0-26	SI	419240	WELL	SI	02/01/2021	GW	123-32197	RODMAN BRUNTZ 2-4-26	SI	473689	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC	473690	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC	473691	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC	473692	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC	473693	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC	473694	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																												
251674	WELL	SI	02/01/2021	GW	123-19477	RODMAN-BRUNTZ 12-26	SI																																																																																																												
419180	WELL	SI	02/01/2021	GW	123-32168	RODMAN BRUNTZ 22-26	SI																																																																																																												
419189	WELL	SI	02/01/2021	GW	123-32172	RODMAN BRUNTZ 11-26	SI																																																																																																												
419193	WELL	SI	02/01/2021	GW	123-32175	RODMAN BRUNTZ 0-2-26	SI																																																																																																												
419208	WELL	SI	02/01/2021	GW	123-32182	RODMAN BRUNTZ 0-4-26	SI																																																																																																												
419218	WELL	SI	07/01/2021	GW	123-32188	RODMAN BRUNTZ 2-0-26	SI																																																																																																												
419240	WELL	SI	02/01/2021	GW	123-32197	RODMAN BRUNTZ 2-4-26	SI																																																																																																												
473689	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC																																																																																																												
473690	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC																																																																																																												
473691	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC																																																																																																												
473692	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC																																																																																																												
473693	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC																																																																																																												
473694	OFF- LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 26H-D266 FAC	AC																																																																																																												
<b>General Comment:</b>  																																																																																																																			

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	chain link		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	chain link		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	chainlink, shared with Separators		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	barb wire, shared with Separators		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 20		
Comment:	automation		
Corrective Action:		Date:	
Type: Pig Station	# 1		

Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 8		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 15		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment: cards in meter houses indicate current calibration			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment: partially exposed at surface			
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 3		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	OTHER	STEEL AST		40.111270,-104.749490	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	800 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	230 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">shares containment with condensate tanks</a>				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
123-32168
123-32188
123-32197
123-19477
123-32175
123-32172
123-32182

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**

Facility ID: 251674 Type: WELL API Number: 123-19477 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/25/2021

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 419180 Type: WELL API Number: 123-32168 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/25/2021

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 419189 Type: WELL API Number: 123-32172 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/25/2021

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 419193 Type: WELL API Number: 123-32175 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 08/25/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 419208 Type: WELL API Number: 123-32182 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 08/25/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 419218 Type: WELL API Number: 123-32188 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 08/25/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 419240 Type: WELL API Number: 123-32197 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Corrective Action: 

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 08/25/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: Corrective Action: 

Date: \_\_\_\_\_

Facility ID: 473689 Type: OFF- API Number: - Status: AC Insp. Status: ACFacility ID: 473690 Type: OFF- API Number: - Status: AC Insp. Status: ACFacility ID: 473691 Type: OFF- API Number: - Status: AC Insp. Status: ACFacility ID: 473692 Type: OFF- API Number: - Status: AC Insp. Status: ACFacility ID: 473693 Type: OFF- API Number: - Status: AC Insp. Status: ACFacility ID: 473694 Type: OFF- API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 11/22/2021 at approximately 1520 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone Peak Resources location:</p> <p style="text-align: right;">Rodman-Bruntz 12-26:</p> <p>API #05-123-19477.</p> <p>County: Weld.</p> <p>While there, I observed a Multi-well Pad and Tank Battery, SI at the time of inspection. During this inspection no compliance issues were observed:</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	11/22/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304521	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5587967">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5587967</a>