

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402877549

Date Received:

11/23/2021

Spill report taken by:

Spill/Release Point ID:

## SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

### OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Operator No: 47120	<b>Phone Numbers</b>
Address: P O BOX 173779		Phone: (970) 336-3500
City: DENVER State: CO Zip: 80217-3779		Mobile: (970) 515-1698
Contact Person: Gregroy Hamilton		Email: Gregory.Hamilton@ox.com

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402877549

Initial Report Date: 11/22/2021 Date of Discovery: 11/22/2021 Spill Type: Historical Release

#### Spill/Release Point Location:

QTRQTR SWNE SEC 14 TWP 3N RNG 67W MERIDIAN 6

Latitude: 40.227220 Longitude: -104.854050

Municipality (if within municipal boundaries): Platteville County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

#### Reference Location:

Facility Type: FLOWLINE SYSTEM

☒ Facility/Location ID No 336649

Spill/Release Point Name: West Farm 2-14A Flowline Release

☐ Well API No. (Only if the reference facility is well) 05- -☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): Unknown

Estimated Condensate Spill Volume(bbl): Unknown

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&amp;P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Has the subject Spill/Release been controlled at the time of reporting? Yes

#### Land Use:

Current Land Use: NON-CROP LAND

Other(Specify):

Weather Condition: Fair, ~65 degrees F.

Surface Owner: FEE

Other(Specify):

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On November 22, 2021, historical soil impacts were discovered during the removal of the flowline associated with the West Farm 2-14A wellhead. Excavation and assessment activities are ongoing. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
11/22/2021	Landowner	Private	-phone	
11/22/2021	CO Parks & Wildlife	B. Marette	-email	
11/22/2021	Town of Platteville	T. Renken	-email	
11/22/2021	Weld County	R. Rudisill	-email	
11/22/2021	Weld County	J. Maxey	-email	

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_

Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_

Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)

Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_

Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_

Was there damage during excavation? \_\_\_\_\_

Was CO 811 notified prior to excavation? \_\_\_\_\_

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_

Yes	Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
	<input type="checkbox"/> The presence of free product or hydrocarbon sheen Surface Water <input type="checkbox"/> The presence of free product or hydrocarbon sheen on Groundwater <input checked="" type="checkbox"/> The presence of contaminated soil in contact with Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Surface water
Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

### SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 11/22/2021		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL			<input checked="" type="checkbox"/>
CONDENSATE			<input checked="" type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls &amp; floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>5</u>		Width of Impact (feet): <u>2</u>	
Depth of Impact (feet BGS): <u>4</u>		Depth of Impact (inches BGS): _____	
How was extent determined?			
<p>During the removal of the West Farm 2-14A flowline on November 19, 2021, soil was screened at five locations along the flowline corridor. Based on field observations and PID readings, soil sample FL-B04@4' was submitted for laboratory analysis of the full COGCC Table 915-1 list of contaminants of concern, using COGCC-approved methods appropriate for detecting the target analytes. Preliminary analytical results indicate that 1,2,4-trimethylbenzene concentration in soil sample FL-B04@4' exceeded the COGCC Table 915-1 Protection of Groundwater Soil Screening Level Concentration. Additional analytical results are pending laboratory analysis and final reporting. On November 19, 2021, groundwater sample FL-GW01 was collected from pothole location FL-B04@4' during flowline removal activities. The groundwater sample was submitted for laboratory analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, 1,2,4- and 1,3,5-trimethylbenzene by United States Environmental Protection Agency (USEPA) Method 8260D. Analytical results indicate that constituent concentrations in sample FL-GW01 were in compliance with COGCC Table 915-1 groundwater standards. Excavation and assessment activities are ongoing and will be summarized in a forthcoming quarterly Form 27-Supplemental Site Investigation and Remediation Workplan under Remediation Project No. 19714 (approved Form 27 Document No. 402781851).</p>			
Soil/Geology Description:			
Clayey sand			

Number Water Wells within 1/2 mile radius: 10

If less than 1 mile, distance in feet to nearest

Water Well	680	None	<input type="checkbox"/>
------------	-----	------	--------------------------

Surface Water	100	None	
---------------	-----	------	---

Wetlands	10	None	<input type="checkbox"/>
----------	----	------	--------------------------

Spirals ☒ None ☐

Livestock	1975	None	
-----------	------	------	---

Occupied Building 1475 None 

Additional Spill Details Not Provided Above:

A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1. The groundwater sample location is illustrated on Figure 2. Soil and groundwater sample location and field screening data are provided in Table 1. Groundwater analytical results are summarized in Table 2. The preliminary laboratory analytical report is provided as Attachment A. Field notes and a photographic log are provided as Attachment B. The State Notification email is provided as Attachment C.

## CORRECTIVE ACTIONS

#1 Supplemental Report Date: 11/22/2021

Root Cause of Spill/Release	Unknown (Historical)
-----------------------------	----------------------

Other (specify) \_\_\_\_\_

Type of Equipment at Point of Spill/Release: Wellhead Line

If "Other" selected above, specify or describe here:

Describe Incident & Root Cause (include specific equipment and point of failure)

Historical impacts were discovered during the removal of the flowline associated with the West Farm 2-14A wellhead.

Describe measures taken to prevent the problem(s) from reoccurring:

Site infrastructure has been removed and will not be replaced.

Volume of Soil Excavated (cubic yards):

Disposition of Excavated Soil (attach documentation)	<input type="checkbox"/> Offsite Disposal	<input type="checkbox"/> Onsite Treatment

☐ Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls):

Volume of Impacted Surface Water Removed (bbbs):

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☐ Corrective Actions Completed (documentation attached, check all that apply)

☐ Horizontal and Vertical extents of impacts have been delineated.

☐ Documentation of compliance with Table 915-1 is attached.

☐ All E&P Waste has been properly treated or disposed.

☒ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: 19714

☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

**OPERATOR COMMENTS:**

Excavation and assessment activities are ongoing and will be summarized in a forthcoming Form 27-Supplemental within 90-days of the release discovery date.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Gregroy Hamilton

Title: Environmental Consultant Date: 11/23/2021 Email: Gregory\_Hamilton@oxy.com

**COA Type**

**Description**

--	--

**Attachment List**

**Att Doc Num**

**Name**

402877549	FORM 19 SUBMITTED
402878309	CORRESPONDENCE
402878312	PHOTO DOCUMENTATION
402878313	SITE MAP
402878335	ANALYTICAL RESULTS
402878338	GROUND WATER SAMPLE LOCATION MAP
402878340	OTHER
402878341	ANALYTICAL RESULTS

Total Attach: 8 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)