

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S96W /36SWNE

Location ID: 335177




Photo #5218 from entrance to location.




Photo #5219 from entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S96W /36SWNE

Location ID: 335177



**Photo #5220 Load out line open ended and not capped.**



**Photo #5221 Debris in tank containment.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources