

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707



Photo 1 – Gas Engine House



Photo 2 – Gas Engine House

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707



Photo 3 – Wellhead



Photo 4 – Label has faded



Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707



Photo 5 – ECDs and Gas Meter



Photo 6 – Heater Treater

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707



Photo 7 – Tank Battery



Photo 8 – Tank Battery Sign

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707




Photo 9 – Far West Tank – Content and Capacity Labels missing



Photo 10 – Engine Exhaust