

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S96W /1SENE

Location ID: 334162



Photo #5243 from entrance to location.



Photo #5244 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S96W /1SENE

Location ID: 334162



Photo #5245 No battery sign located a the tank battery.



Photo #4344 from inspection #699803363 inspection conducted on 7/7/21.