



Captiva
Energy Partners

Captiva Energy Partners LLC


Inspection Compliance Photos

Date of COGCC Inspection: November 1, 2021

Location Name: McCoy Pad 13-33

Location ID: 428105

November 15, 2021



McCoy Pad 13-33
Location ID: 428105

Dead weed debris has
been removed as of
Nov. 15, 2021



McCoy Pad 13-33
Location ID: 428105

Bird screen on McCoy 13-33
separator has been replaced
as of Nov. 15, 2021



Dead weed debris has
been removed as of Nov.
15, 2021

