



## Inspection Photos

Location Name: McClung 29-10 Pad

Location ID: 335048

Inspection Date: November 11, 2021

Location sign.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: McClung 29-10 Pad  
Location ID: 335048  
Inspection Date: November 11, 2021

Tank battery looking southwest.

Nov 11, 2021 11:52:  
39.41557345N 107.79553  
Altitude: 23  
Speed: 0.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





### Inspection Photos

Location Name: McClung 29-10 Pad

Location ID: 335048

Inspection Date: November 11, 2021

Trash on location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





### Inspection Photos

Location Name: McClung 29-10 Pad

Location ID: 335048

Inspection Date: November 11, 2021

Oily rag, trash on location.

Nov 11, 2021 11:53  
39.4155105N 107.79561  
Altitude: 23  
Speed: 4.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





### Inspection Photos

Location Name: McClung 29-10 Pad

Location ID: 335048

Inspection Date: November 11, 2021

**Evidence of livestock and wildlife  
on location.**

Nov 11, 2021 12:04:13 PM  
39.41592065N 107.79626206W  
Altitude: 2322.0m  
Speed: 0.0km/h



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





### Inspection Photos

Location Name: McClung 29-10 Pad

Location ID: 335048

Inspection Date: November 11, 2021

**Evidence of livestock and wildlife on location with wells 05-045-15910, 05-045-15911 and 05-045-15912 in the background.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: McClung 29-10 Pad  
Location ID: 335048  
Inspection Date: November 11, 2021

Sign not posted at well API 05-045-15912 McClung 29-11A.

TEP Rocky Mountain LLC  
**McClung 29-11A**  
SL: NWSE Sec. 29, T7S-R93W  
BHL: NESW Sec 29, T7S-R93W  
CA No:  
Lease No: Fee  
API No: 05-045-15912  
Garfield County, Colorado  
Emergency Contact 970-283-1977  
Emergency Services 911

Nov 11, 2021 11:55  
39.41576645N 107.79605  
Altitude: 23  
Speed: 0.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Nov 11, 2021 11:56:  
39.41595405N 107.7962  
Altitude:23  
Speed:0.

Inspection Photos  
Location Name: McClung 29-10 Pad  
Location ID: 335048  
Inspection Date: November 11, 2021

Looking north from the location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Nov 11, 2021 11:56:  
39.4159575N 107.79620  
Altitude: 23  
Speed: 0.

**Inspection Photos**  
**Location Name:** McClung 29-10 Pad  
**Location ID:** 335048  
**Inspection Date:** November 11, 2021

**Looking northwest from the  
location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: McClung 29-10 Pad  
Location ID: 335048  
Inspection Date: November 11, 2021

Location looking east.

Nov 11, 2021 12:00:  
39.41636322N 107.79670  
Altitude:23  
Speed:0.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





### Inspection Photos

Location Name: McClung 29-10 Pad

Location ID: 335048

Inspection Date: November 11, 2021

**Arroyo located approximately 60 feet west of the previous photo.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources