

Inspection Photos
Location Name: State 8-7
Location ID: 326971



Photo 1 – Pumping Unit



Photo 2 – Separator and Gas Meter

Inspection Photos
Location Name: State 8-7
Location ID: 326971



Photo 3 – Tank Battery

Photo 4 – Tank Battery – Produced Water Label is fading

Inspection Photos
Location Name: State 8-7
Location ID: 326971



Photo 5 – Tank Battery Sign