


**Inspection Photos**  
**Location Name: Vera #1**  
**Location ID: 318556**



**Photo 1 – Separator**



**Photo 2 – Calibration is up to date**

**Inspection Photos**  
**Location Name: Vera #1**  
**Location ID: 318556**



**Photo 3 – Tank Battery**



**Photo 4 – Tank Battery Sign**



**Inspection Photos**  
**Location Name: Vera #1**  
**Location ID: 318556**



**Photo 5 – Wellhead**