

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2021

Submitted Date:

11/24/2021

Document Number:

701004030**FIELD INSPECTION FORM**Loc ID 321816 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 51065Name of Operator: LOEB LLC* HERMAN LAddress: P O BOX 838City: LAWRENCEVILLE State: IL Zip: 62439**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pelton, Shane	620-617-5870	shane@loeboil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208102	WELL	PR	10/17/1989	OW	017-07037	EVANS R 1	PR

General Comment:[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 0		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 0		
Comment:	Removed from location		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0		FIBERGLASS AST		38.649710,-102.088290
Comment:	Removed from location				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspected Facilities									
Facility ID:	208102	Type:	WELL	API Number:	017-07037	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (Kriss 2 & 3, Evans Q #2 & #4, Evans R #1) 570' E @ 38.649810/-102.087760								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701004036	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5589588