

Inspection Photos
Operator: Simcoe
API: 067-08834
Date: 11/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Approximately 15 Russian olive trees need to be removed. Revegetation is progressing with sand dropseed, western wheatgrass, intermediate wheatgrass.



Photo 3. View of pipes within the western project area need to be removed.



Photo 4. View of Canada thistles need to be controlled within the southwestern project area, approximately 150 individuals observed.



Photo 5. View the southern project area from the southwestern corner facing eastward.



Photo 6. View of reference area comprised of pinyon and juniper woodland with gambel oak, western wheatgrass, and mountain mahogany in the understory.