

Inspection Photos
Operator: Simcoe
API: 067-06957
Date: 11/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of Russian thistle debris around facilities, needs to be removed.



Photo 3. View of more weed debris on the well pad and around facilities, needs to be removed.



Photo 4. View of the eastern project area from the southeastern corner facing northward. Wood debris, and farm equipment stored around the perimeter of the project area.



Photo 5. View of more farm equipment stored within the southwestern well pad area.



Photo 6. View of reference area comprised of irrigated grass and alfalafa field.