

# Inspection Photos

API: 071-09004

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/29/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09004 | Date: 11/29/2021

## Inspection Photos



**Photo 1.** Facing toward the southwest side of the location. This area has not established vegetation cover and has been reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09004 | Date: 11/29/2021



## Inspection Photos



**Photo 2.** There was seed and hand raking observed in the area shown in previous photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09004 | Date: 11/29/2021



## Inspection Photos



**Photo 3.** Facing southeast toward the upper portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09004 | Date: 11/29/2021



## Inspection Photos



**Photo 4.** Facing southeast toward the lower portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09004 | Date: 11/29/2021