

Inspection Photos

API: 071-09540

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/29/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09540 | Date: 11/29/2021

Inspection Photos



Photo 1. Facing northwest along the road traveling to the location. The road has been graded and culverts have been maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09540 | Date: 11/29/2021

Inspection Photos



Photo 2. The culverts along the road have been cleaned out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09540 | Date: 11/29/2021

Inspection Photos



Photo 3. Facing northwest along the road traveling to the location. The road has been graded and culverts have been maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09540 | Date: 11/29/2021

Inspection Photos



Photo 4. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09540 | Date: 11/29/2021

Inspection Photos



Photo 5. Well sign posted at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09540 | Date: 11/29/2021