

Inspection Photos

API: 071-09549

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/29/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 11/29/2021

Inspection Photos



Photo 1. Facing northwest along the preexisting road traveling to the location. There is a pipe riser that still remains at Lat/Long:37.23799,-105.00365. There are no active sites beyond this point and the equipment needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 11/29/2021

Inspection Photos



Photo 2. Further along the road other pipe risers have been removed and disturbance was reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 11/29/2021

Inspection Photos



Photo 3. The culverts along the road have been cleaned out and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 11/29/2021

Inspection Photos



Photo 4. The metal valve box was removed and disturbance reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 11/29/2021

Inspection Photos



Photo 5. There were two additional areas where risers were removed up the canyon at Lat/Long:37.26203,-105.01578.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 11/29/2021