

Inspection Photos
Location Name: Dwight G Hanks Tank Battery
Location ID: 317655



Photo 1 TB sign



Photo 2 TB

Inspection Photos
Location Name: Dwight G Hanks Tank Battery
Location ID: 317655



Photo 3 TB



Photo 4 TB

Inspection Photos
Location Name: Dwight G Hanks Tank Battery
Location ID: 317655



Photo 5 Stained soil under TB flowlines



Photo 6 Stained soil around TB flow line

Inspection Photos
Location Name: Dwight G Hanks Tank Battery
Location ID: 317655



Photo 7 Stained soil under TB load line



Photo 8 Stained soil around Crude tank

Inspection Photos
Location Name: Dwight G Hanks Tank Battery
Location ID: 317655



Photo 9 flow line manifold and aux. pump



Photo 10 Stained soil around manifold flowlines

Inspection Photos
Location Name: Dwight G Hanks Tank Battery
Location ID: 317655



Photo 11 Horiz. Heated Separators/ Heater treaters



Photo 12 Stained soil inside heater treater housing

Inspection Photos
Location Name: Dwight G Hanks Tank Battery
Location ID: 317655



Photo 13 VRT



Photo 14 ECDs