

Inspection Photos
Location Name: Kildow C 31-7X
Location ID: 306309



Photo #1 Well



Photo #2 West production tank is missing capacity label and needs replaced