

Inspection Photos
Location Name: Federal-Blue Gravel 1-23
Location ID: 312880



Photo 1. Overview of location taken facing southeast. Dried annual weeds.



Photo 2. No bradenhead access apparent.



Inspection Photos
Location Name: Federal-Blue Gravel 1-23
Location ID: 312880



Photo 3. Animal burrows in berm.



Photo 4. Holes in tank.

