

Inspection Photos
Location Name: Grassy Creek Coal Co 1
Location ID: 316752



Photo 1. Overview of location taken facing south.



Photo 2. Example of sediment migration on access road.

