

Inspection Photos
Operator: Logos Operating
API: 067-05476
Date: 11/30/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope, from the southeastern corner facing westward. Revegetation is progressing rubber rabbitbrush, western wheatgrass, and smooth brome.



Photo 5. View of reference area comprised of sagebrush shrubland, with snakeweed, buckwheat, western wheatgrass, Indian ricegrass, purple threeawn, and squirreltail.