

**Inspection Photos**  
**Operator: Logos Operating**  
**API: 067-08137**  
**Date: 11/30/2021**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing here with western wheatgrass and rubber rabbitbrush.



Photo 3. View of area within the southern fill slope with poor vegetative cover and dense Russian thistle.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of western wheatgrass, Indian ricegrass, black sage, prickly pear, and purple threeawn.