

Inspection Photos
Operator: Logos Operating
API: 067-08297
Date: 11/30/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with big sagebrush, western wheatgrass, Indian ricegrass, and sand dropseed.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland mosaic, with understory of western wheatgrass, Indian ricegrass, black sage, prickly pear, and purple threeawn.