

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Both pits capacity labels are faded and need replaced. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	12/13/2021

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Wire		
Corrective Action:		Date:	

Equipment:

Type	#		corrective date
Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV CONCRETE		
Comment:	capacity labels are faded and need replaced.				

Corrective Action:	Date:
--------------------	-------

Paint

Condition		
Other (Content)		
Other (Capacity)	48 BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.285000,-104.565300
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 481155 Type: TANK API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 12/2/21 at approximately 0842hrs, I, Inspector Adam Burns, Conducted an on-site inspection at 28-4N-64W SWNW Hanscome TB of Noble Energy, at Facility ID # 481155 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Both pits capacity labels are faded and need replaced. Install sign to comply with Rule 605.h. With a corrective action date of 12/13/21 See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	12/02/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699104879	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5594375