

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 481139 Type: TANK API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 12/2/21 at approximately 1022hrs I, Inspector Adam Burns, Conducted an on-site inspection at 21-4N-64W SWNW Leonard Tank Battery of Noble Energy Facility ID: 481139 in Weld County, Colorado. While there, I observed a facility that is SI. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.</p>	burnsa	12/02/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699104887	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5594379