

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31SWSE

Location ID: 334917



Photo #5295 from entrance to location.



Photo #5296 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31SWSE

Location ID: 334917



Photo #4406 from inspection #699803393 conducted on 7/13/21.



Photo #5297 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31SWSE

Location ID: 334917



Photo #4407 from inspection #699803393 conducted on 7/13/21.



Photo #5298 Insufficient tracking control at entrance to location.