

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RADEL-68S96W /11NWSW

Location ID: 334347



Photo #5301 from entrance to location.



Photo #5302 from entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RADEL-68S96W /11NWSW

Location ID: 334347



Photo #3688 from inspection #699803019 conducted on 5/4/21.



Photo #5303 No battery sign located at the tank battery.