

Inspection Photos
Location Name: Trail Gulch Unit 1090 30
Spill/Release Point ID: 481083



Trail Gulch Unit 1090 30 location entrance.



Trail Gulch Unit 1090 30 location photo. Area impacted by Spill/Release Point ID #481083 evident on cut slope.

Inspection Photos
Location Name: Trail Gulch Unit 1090 30
Spill/Release Point ID: 481083



Trail Gulch Unit 1090 30 flow back operations taking place during this inspection.



Trail Gulch Unit 1090 30 H2 flow back equipment.

Inspection Photos
Location Name: Trail Gulch Unit 1090 30
Spill/Release Point ID: 481083



Close up of sand on cut slope.



Trail Gulch Unit 1090 30 H2.