

# Interim Reclamation and Stormwater Inspection

December 1, 2021

Operator: EDGE ENERGY II LLC- #10671

Location ID: 456286

Inspection Document #: 697503530

Weld County, CO

NENE Section 29 T11N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Deporter /29-A Pad  
Location ID: 456286



**Photo 1.** Photo taken from location, facing Northeast. Photo illustrates Operator is starting to mobilize equipment to location.



Inspection Photos  
Location Name: Deporter /29-A Pad  
Location ID: 456286



**Photo 2.** Photo taken from a portion of the interim reclamation area. Photo illustrates Common rye that has matured and gone to seed. This was observed throughout the interim reclamation areas.




Inspection Photos  
Location Name: Deporter /29-A Pad  
Location ID: 456286



**Photo 3.** Photo taken from the southwestern location, facing Southwest. Photo illustrates Operator has enlarged the previous sediment trap to a stormwater pond with a stabilized outlet.



**Photo 4.** Photo taken from the southwestern location, facing East. Photo illustrates the eastern stormwater pond.



**Photo 5.** Photo illustrates the engineered designed 8250 CF stormwater pond



Inspection Photos  
Location Name: Deporter /29-A Pad  
Location ID: 456286



**Photo 6.** Photo taken from the southern access road, facing Northeast. Photo illustrates Operator has stabilized the cut slope along the access road.



**Photo 7.** Photo taken from the southern access road on 8/23/2021, facing Northeast.

Inspection Photos  
Location Name: Deporter /29-A Pad  
Location ID: 456286



**Photo 8.** Photo taken from the entrance of location, facing West. Photo illustrates the cattle guard has not yet been replaced but there are plans to replace with a used cattle guard from a nearby PA location.

