

# Final Reclamation Inspection

October 14th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323008

Inspection Document #: 701900198

Weld County, CO

NWSW Section 13 T5N R65W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Andrew Hop 1  
Location ID: 323008



**Photo 1.** 2016 aerial imagery of the well pad, access road and tank battery (north is up). Note: The tank battery and well pad now exist in a campground.



Inspection Photos  
Location Name: Andrew Hop 1  
Location ID: 323008



**Photo 2.** Overview photo of the well pad taken at ground level from the south end looking north. Note: well pad resides on the edge of an active campground and has been seeded with an unknown perennial bunchgrass when the land transitioned from agriculture to campground use. Fence in background of photo is not associated with oil and gas operations.




Inspection Photos  
Location Name: Andrew Hop 1  
Location ID: 323008



**Photo 3.** Photos taken from the middle of the well pad. Left photo is facing north and right photo facing east.



Inspection Photos  
Location Name: Andrew Hop 1  
Location ID: 323008



**Photo 4.** Photos taken from the middle of the well pad. Left photo facing south and right photo facing west.



Inspection Photos  
Location Name: Andrew Hop 1  
Location ID: 323008



**Photo 5.** Reference photo to the east of the well pad.



Inspection Photos  
Location Name: Andrew Hop 1  
Location ID: 323008



**Photo 6.** Tank battery overview photo taken at ground level from west of the tank battery looking south. Note: the reclaimed tank battery now resides between two dirt roads in an active campground.



Inspection Photos  
Location Name: Andrew Hop 1  
Location ID: 323008



**Photo 7.** Photos taken from the middle of the tank battery. Left photo facing north and right photo facing east (see description under photo 8).



Inspection Photos  
Location Name: Andrew Hop 1  
Location ID: 323008



**Photo 8.** Photos taken from the middle of the tank battery. Left photo facing south and right photo facing west.



Inspection Photos  
Location Name: Andrew Hop 1  
Location ID: 323008



**Photo 9.** Reference area to the north of the tank battery.