



Inspection Photos  
Location Name: River Ranch A Pad  
Location ID: 336014  
Spill/Release ID: 480927  
Inspection Date: November 17, 2021

Location sign.

Nov 17, 2021 11:59:  
39.53878779N 107.6981  
Altitude:16  
Speed:0.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Nov 17, 2021 12:03  
39.53850872N 107.69783  
Altitude: 16  
Speed: 0.

Inspection Photos  
Location Name: River Ranch A Pad  
Location ID: 336014  
Spill/Release ID: 480927  
Inspection Date: November 17, 2021

#### Photo 1

Spill/release point looking southeast, note the 10-inch produced water poly line riser and the marshy area in the background.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



### Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Inspection Date: November 17, 2021

### Photo 2

Marshy area located southeast of the spill/release point. Note the boom located within the marshy area.

Nov 17, 2021 12:21:  
39.53836227N 107.69758  
Altitude:16  
Speed:0.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



### Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Inspection Date: November 17, 2021

### Photo 3

Marshy area located southeast of the spill/release point. Note the the hydrocarbon sheen present on the surface water.

Nov 17, 2021 12:14:39.53845025N 107.69749  
Altitude:16  
Speed:0.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



### Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Inspection Date: November 17, 2021

### Photo 4

Marshy area located southeast of the spill/release point. Note the the hydrocarbon sheen present on the surface water.

Nov 17, 2021 12:11:  
39.53847755N 107.69757  
Altitude:16  
Speed:1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Nov 17, 2021 12:16  
39.53851756N 107.69759  
Altitude: 16  
Speed 0.

Inspection Photos  
Location Name: River Ranch A Pad  
Location ID: 336014  
Spill/Release ID: 480927  
Inspection Date: November 17, 2021

#### Photo 5

Apparent impacts and paraffin present around the 10-inch produced water poly line riser where the spill/release occurred.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



### Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Inspection Date: November 17, 2021

### Photo 6

Evidence of wildlife around the spill/release area.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



### Inspection Photos

Location Name: River Ranch A Pad

Location ID: 336014

Spill/Release ID: 480927

Inspection Date: November 17, 2021

### Photo 7

BMPs in disrepair. Note the River Ranch A Pad tank battery in the background.

Nov 17, 2021 12:03:  
39.53841592N 107.69788  
Altitude:16  
Speed:0.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Nov 17, 2021 12:03  
39.53836327N 107.69793  
Altitude: 16  
Speed: 0

Inspection Photos  
Location Name: River Ranch A Pad  
Location ID: 336014  
Spill/Release ID: 480927  
Inspection Date: November 17, 2021

**Photo 8**  
**BMPs in disrepair.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources