

Inspection Photos
Location Name: Elmer Kauffman #2
Location ID: 317706



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Elmer Kauffman #2
Location ID: 317706



Photo 3 Electric panel

Photo 4 tall dead weeds around wellsite ROW

Inspection Photos
Location Name: Elmer Kauffman #2
Location ID: 317706



Photo 5 wees all along TB access rd.

Photo 6 TB sign

Inspection Photos
Location Name: Elmer Kauffman #2
Location ID: 317706




Photo 7 Dead weeds on TB berm.

Photo 8 Dead weeds by the Horiz. Heated Sep.

Inspection Photos
Location Name: Elmer Kauffman #2
Location ID: 317706



Colorado Oil & Gas Conservation Commission
 US-6, Keenesburg, CO 80643, USA
 40.13579, -104.47966, 4870.6ft, 215°
 12/02/2021 11:38:14



dep MESS			
Station Number:	214241		
Station Name:	Kauffman 2,3,4		
Static Pressure:	0.500"		
Calibrated Orifice Size:	1.250"		
Differential Pressure:	0.150"		
Calibrated Differential:	0.150"		
Temperature Pressure:	0.150"		
Meter Run Size:	1.032		
Events			
Date	Orifice Size	Test Date	
12/21/15	1.250	12/21/15	
5/19/16	1.250	5/19/16	
11/16/16	1.250	11/16/16	
5/23/17	1.250	5/23/17	
5/24/18	1.250	5/24/18	
11/28/18	1.250	11/28/18	
11/18/19	1.250	11/18/19	
5/20/20	1.250	5/20/20	
	1.250	2/2/21	

Colorado Oil & Gas Conservation Commission
 US-6, Keenesburg, CO 80643, USA
 40.13576, -104.47973, 4858.6ft, 289°
 12/02/2021 11:38:34

Photo 9 Dead weeds around Gas Meter Run.

Photo 10 card in meter house indicates current calibration

Inspection Photos
Location Name: Elmer Kauffman #2
Location ID: 317706



Photo 11 ECD