

Inspection Photos

12/01/2021

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 335950

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 335950



Photo 1: Photos taken from the northwestern end of the Location, facing west and north. Photos show Operator has installed a sediment trap in conjunction with a slope drain; erosion degradation repaired.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 335950



Photo 2: Armored slope drain outlet.