

Inspection Photos

12/01/2021

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 383337

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 383337



Photo 1: Photos show Operator placed gravel on select sections of the Location; from the entrance leading south around the wells. Control measures to stabilize the entire Location, minimize tracking and offsite sediment transport per good engineering practices remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 383337



Photo 2: Photos show Operator placed gravel on select sections of the Location; from the entrance leading south around the wells. Control measures to stabilize the entire Location, minimize tracking and offsite sediment transport per good engineering practices remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 383337



Photo 3: Photo taken from the east end of the Location. Photo provides example showing control measures to stabilize the entire Location, minimize tracking and offsite sediment transport per good engineering practices remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 383337



Photo 4: Sediment trap has been re-constructed with an appropriate engineered outlet.