

Inspection Photos
Location Name: Hassler #27
Location ID: 322259



Photo 1 loc pic



Photo 2 stained soil around well head

Inspection Photos
Location Name: Hassler #27
Location ID: 322259



Photo 3 no markings, placards on crude oil tank



Photo 4 Debris dead weeds in containment.

Inspection Photos
Location Name: Hassler #27
Location ID: 322259



Photo 5 Stained soil under inspection hatch to tank.

