

**Inspection Photos**  
**Operator: Kinder Morgan**  
**API: 083-06722**  
**Date: 12/2/2021**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with western wheatgrass and crested wheatgrass.



Photo 3. View of the southern project area from the southwestern corner facing eastward. Southern project area is in use as cultivated field that is not vegetated at this time.



Photo 4. View of reference area comprised of open crop fields with multiple uses, some plowed for dryland crops such as wheat and others supporting perennial grasses such as crested wheatgrass and western wheatgrass.