

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2021

Submitted Date:

12/04/2021

Document Number:

688311699

**FIELD INSPECTION FORM**
 Loc ID 479191 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10243

Name of Operator: GMT EXPLORATION COMPANY LLC

Address: 1560 BROADWAY STE 2000

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Cox, BJ	303-586-9274	bjcox@gmtexploration.com	
Eberhardt, Whitney	303-586-9289	w.eberhardt@gmtexploration.com	Principal Agent
Andrews, Doug		doug.andrews@state.co.us	COGCC OGLA

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480437	WELL	XX	08/16/2021		039-06733	Crystal 6-65 22-10 1HN	CI

**General Comment:**

Inspection to verify access road relocation per the landowner's request and Form 4 #402885042.

Landowner requested that the access road be a straight line to the location vs. following the banks of Coal Creek (see attached map). The pad was under construction with a ditch installed around the pad prior to beginning of construction. The access road had not been constructed at time of this inspection. See attached photos that include GPS coordinates and elevations. The Crystal pad is in a pasture with cattle and operator stated that a fence (livestock at other locations) would be constructed. Topsoil was a loam.

Floodplain (FEMA) areas in Coal Creek are mapped near the Crystal pad entrance and 253' from SE most well on the Crystal pad (039-06752). Wetlands are mapped in Coal Creek 875' south of southern row of wells on the Crystal pad. Per Rule 1202c the Crystal pad is in High Priority Habitat for Aquatic Native Species Conservation Waters. Per Rule 1202d the Crystal pad is in Density Habitats for the Mule Deer Severe Winter Range. The Operator stated that they contacted the regulatory agency about the floodplain and the Mule Deer habitat.



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Rip Rap	Pass			
Compaction	Pass	Culverts	Pass			
		Seeding	Pass			
		Blankets	Pass			

Comment: [Top soil stock piles are present.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688311708	GMT Crystal Access Road Map	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596278">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596278</a>
688311709	GMT Exploration Crystal 6-65 22-10 1HN	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596279">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596279</a>