

Inspection Photos

API: 009-06439

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 11/30/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06439 | Date: 11/30/2021

Inspection Photos



Photo 1. Facing southeast toward the location. The access road continues thru the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 11/30/2021

Inspection Photos



Photo 2. There is a plastic pipe with t-post at north side of the location shown at red arrow. This needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 11/30/2021

Inspection Photos



Photo 3. Facing northeast near the location. There is culvert with pipeline valves that appear to be associated with the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 11/30/2021

Inspection Photos



Photo 4. Facing west at the south side of the location. This area consists mostly of undesirable weeds (Russian thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 11/30/2021

Inspection Photos



Photo 5. Facing north at the south side of the location. This area consists mostly of undesirable weeds (Russian thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 11/30/2021

Inspection Photos



Photo 6. View of undesirable weeds at the south side of the location. The weed debris needs to be removed and the area reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 11/30/2021

Inspection Photos




Photo 7. There is a plastic pipe sticking out of the ground approx. 200' southeast of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 11/30/2021

Inspection Photos



Photo 8. The equipment previously observed was removed however reclamation has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 11/30/2021

Inspection Photos



Photo 9. Facing toward the surrounding undisturbed reference area which consists of Blue grama, Sand dropseed, Prairie threeawn, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 11/30/2021