

Inspection Photos

API: 099-06066

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 11/30/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06066 | Date: 11/30/2021

Inspection Photos



Photo 1. Facing east. There is abandoned gas separator that remains at the location. There is also undesirable weeds growing around the abandoned equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06066 | Date: 11/30/2021

Inspection Photos



Photo 2. Facing west. There is abandoned gas separator that remains at the location. There is also undesirable weeds growing around the abandoned equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06066 | Date: 11/30/2021