

# Inspection Photos

API: 099-06255

Operator: BERRY\* WALTER V DBA BERRY  
ENERGY INC

Inspection Date: 11/30/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 099-06255 | Date: 11/30/2021

## Inspection Photos



**Photo 1.** South side of the location facing northeast. This area does not have vegetation establishment which is approximately 100'x50'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06255 | Date: 11/30/2021



## Inspection Photos



**Photo 2.** There is a pipe riser that remains at the north side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06255 | Date: 11/30/2021

## Inspection Photos



**Photo 3.** Facing northwest approximately 1400 ft. northwest of the location. There are two pipe risers associated with the well site that have not been removed. All equipment/risers must be removed. Lat/Long:37.78859,-102.44911.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06255 | Date: 11/30/2021