

Inspection Photos

API: 099-06354

Operator: BERRY* WALTER V DBA BERRY
ENERGY INC

Inspection Date: 11/30/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 11/30/2021

Inspection Photos



Photo 1. Drone aerial photo facing northwest toward the abandoned well location. The pits were never backfilled and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 11/30/2021

Inspection Photos



Photo 2. Facing northwest downward toward the pit. The berms of the pit are approximately 150'x150' in size.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 11/30/2021

Inspection Photos



Photo 3. Facing northeast toward the pit. There is trench shown at red arrow which is diverted toward the pit from the location of the abandoned well. This area was never backfilled and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 11/30/2021

Inspection Photos



Photo 4. Facing northwest toward a lined pit which is approximately 100'x30' in size. There is degraded liner debris that remains in the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 11/30/2021

Inspection Photos



Photo 5. Drone aerial photo facing southeast toward the abandoned well location. The pits were never backfilled and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 11/30/2021