

# Inspection Photos

ID: 431431

Operator: STRACHAN EXPLORATION INC

Inspection Date: 12/1/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

ID: 431431 | Date: 12/1/2021

## Inspection Photos



**Photo 1.** Facing toward the tank battery. A sign has been posted and labels have been paced on the tank.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 431431 | Date: 12/1/2021

## Inspection Photos



**Photo 2.** Facing toward the compressor.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 431431 | Date: 12/1/2021



## Inspection Photos



**Photo 3.** There is oil and trash inside the secondary containment. This needs to be cleaned up and properly disposed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 431431 | Date: 12/1/2021

## Inspection Photos



**Photo 4.** There is still oily rags and oil stained soil around the compressor.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 431431 | Date: 12/1/2021



## Inspection Photos



**Photo 5.** Facing toward the compressor.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 431431 | Date: 12/1/2021