

Inspection Photos

API: 099-06215

Operator: BERRY* WALTER V DBA BERRY
ENERGY INC

Inspection Date: 12/1/2021



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 12/1/2021

Inspection Photos



Photo 1. Drone aerial photo facing southeast toward the location shown at red arrow. The two track access road remains to the location.



Photo 2. Drone aerial photo facing opposite direction toward the southwest showing the two track access road that remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 12/1/2021

Inspection Photos



Photo 3. Drone aerial photo down toward the abandoned well site location. There are two abandoned meter runs and equipment that remain at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 12/1/2021

Inspection Photos



Photo 4. Drone aerial photo down toward the abandoned well site location. There are two abandoned meter runs and equipment that remain at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 12/1/2021

Inspection Photos



Photo 5. Facing northwest at the abandoned well site. The location consists mostly of undesirable weeds as identified in previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 12/1/2021