

Inspection Photos

API: 099-06215

Operator: BERRY* WALTER V DBA BERRY
ENERGY INC

Inspection Date: 12/1/2021



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 12/1/2021

Inspection Photos



Photo 1. Drone aerial photo facing northwest toward the abandoned well location. The location has not been recontoured and reclaimed. There is erosion occurring along the access road near the location shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 12/1/2021

Inspection Photos




Photo 2. There is an area 150' x 100' with no vegetation shown at red arrow. Additionally the cut slope of the location is shown along the yellow arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 12/1/2021

Inspection Photos



Photo 3. There are abandoned pipe risers that remain at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06215 | Date: 12/1/2021