

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402886808

Date Received:

12/05/2021

Spill report taken by:

NEIDEL, KRIS

Spill/Release Point ID:

481093

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: <u>GULFPORT ENERGY CORPORATION</u>	Operator No: <u>10339</u>	Phone Numbers
Address: <u>3001 QUAIL SPRINGS PARKWAY</u>		Phone: <u>(405) 252-4637</u>
City: <u>OKLAHOMA CITY</u>	State: <u>OK</u>	Zip: <u>73134</u>
Contact Person: <u>Jace Marshall</u>		Mobile: <u>()</u>
		Email: <u>jmarshall@gulfportenergy.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402869934

Initial Report Date: 11/12/2021 Date of Discovery: 11/08/2021 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR NESW SEC 16 TWP 6N RNG 91w MERIDIAN 6

Latitude: 40.476010 Longitude: -107.610770

Municipality (if within municipal boundaries): _____ County: MOFFAT

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Reference Location:

Facility Type: WELL SITE Facility/Location ID No _____

Spill/Release Point Name: State 41-14-1 Well API No. (Only if the reference facility is well) 05-081-07664

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=5 and <100 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: Estimated 5-8 bbls oil and 5-8 bbls of produced water during plugging operation

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LAND Other(Specify): _____

Weather Condition: Cool and Dry

Surface Owner: FEE Other(Specify): _____

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Released fluid while performing plugging operations of the well.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
11/9/2021	COGCC	Kris Neidel	970-846-5097	Thanks for contacting us

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

- No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
- Waters of the State: _____ Public Water System: _____
- Residence or Occupied Structure: _____ Livestock: _____
- Wildlife: _____ Publicly-Maintained Road: _____
- Yes Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
- Yes Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
- No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
- Enter the approximate time of discovery _____ (HH:MM)
- Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____
- Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____
- Enter the Document Number of the Initial Accident Report, Form 22 _____
- Was there damage during excavation? _____
- Was CO 811 notified prior to excavation? _____
- No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
- Estimated Volume of Impacted Solids (cu. yd.): _____
- No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
- The presence of free product or hydrocarbon sheen Surface Water
- The presence of free product or hydrocarbon sheen on Groundwater
- The presence of contaminated soil in contact with Groundwater
- The presence of contaminated soil in contact with Surface water
- No Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.

No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: <u>12/03/2021</u>		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	<u>8</u>	<u> </u>	<input checked="" type="checkbox"/>
CONDENSATE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
PRODUCED WATER	<u>8</u>	<u> </u>	<input checked="" type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): _____		Width of Impact (feet): _____	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
Spill path was observed where the release occurred. Excavation following removal of equipment will determination depth(s) of impact.			
Soil/Geology Description:			
H1 - 0 to 4 inches: silty clay H2 - 4 to 36 inches: clay H3 - 36 to 60 inches: silty clay			
Depth to Groundwater (feet BGS) <u>80</u>		Number Water Wells within 1/2 mile radius: <u>6</u>	
If less than 1 mile, distance in feet to nearest		Water Well <u>682</u> None <input type="checkbox"/>	Surface Water <u>716</u> None <input type="checkbox"/>
		Wetlands <u>902</u> None <input type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>
		Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building <u>588</u> None <input type="checkbox"/>
Additional Spill Details Not Provided Above:			
At around 2230 on 11/8/21 we had just pumped a 208' cement plug on top of a CIBP set at 6489'. While pulling TBG out of cement well kicked, pushing CICB and cement plug up hole 115', by tag the next day. We had well set up to flow CSG to the flat tank and with a gas kick we blew oil and fresh water out of the flat tank on the ground. The 2" valve below washington head on BOP was open as well for well monitoring and blew oil and fresh water out of it around the wellhead. All fluid was contained around the wellhead and equipment. Oil was skimmed with a vac truck and water pulled and put into production tanks on location.			

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

- Basis for Closure:
- Corrective Actions Completed (documentation attached, check all that apply)
 - Horizontal and Vertical extents of impacts have been delineated.
 - Documentation of compliance with Table 915-1 is attached.
 - All E&P Waste has been properly treated or disposed.
 - Work proceeding under an approved Form 27 (Rule 912.c).
Form 27 Remediation Project No: 20718
 - SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

Gulfport is requesting the Form 19 Spill # 481093 be closed and transferred to the approved Form 27 Remediation Project #20718

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Joel Mason
Title: Senior Project Manager Date: 12/05/2021 Email: joel.mason@absarokasolutions.com

Condition of Approval

COA Type

Description

	Work proceeding under 20718 remediation project number.
	REM project #20718 should be updated to incorporate this spill.
2 COAs	

Attachment List

Att Doc Num

Name

402886808	SPILL/RELEASE REPORT(SUPPLEMENTAL)
402886871	AERIAL IMAGE
402886873	PHOTO DOCUMENTATION
402891272	FORM 19 SUBMITTED

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)