

Inspection Photos
Location Name: Hill #8-2
Location ID: 326255



Photo 1 Well sign



Photo 2 Debris: dead weeds along road access

Inspection Photos
Location Name: Hill #8-2
Location ID: 326255



Photo 3 loc pic. Debris: dead weeds on location



Photo 4 Debris: dead weeds on location



Inspection Photos
Location Name: Hill #8-2
Location ID: 326255



Photo 1 Vert sep/meter house



Photo 6 WH

Inspection Photos
Location Name: Hill #8-2
Location ID: 326255



Photo 7 produced water tank and Debris: dead weeds on location.