

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-66S95W /34NWNE

Location ID: 335333



Photo #5320 from entrance to location.



Photo #5321 from entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-66S95W /34NWNE

Location ID: 335333



**Photo #5322 Location lacks stabilization.**



**Photo #5323 Location lacks stabilization.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name: TEP ROCKY MOUNTAIN LLC EXXON-66S95W /34NWNE**

**Location ID: 335333**



**Photo #5325 Insufficient Tracking BMP at entrance to location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources